



REFINISH

Process Chart

Defect Removal by sanding



DIAMOND CUT 3000

COMPOUND 5000

FINAL CUT 9000

ULTRA FINISH 12000



**W
A
X
C
O
A
T**

Heavy Cut

High Gloss

Polishing by rotary or orbital machine